

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	007	013	0000002409	See list below	Appliance outlet	5216	


*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
6183.0002	6183.0003	6183.0013					

2 Type of change

Modification of approval mark.



3 Detailed description of change

Approvals old: 

new: 

Old marking

New marking





4 Reason of change

Harmonisation of Approval Marks.

5 Released date

The change will be rolled-out starting ww 35/2016 (Date code 1635 or higher on label) and lasts approx. 9 months depending on the variant.

6 Impact of change and recommended action

Form	Approval  replaced by 
Fit	No change of fit.
Function	No change of the function.
Production Site	No change of the production side.
Product Label	No label change.
Customer Action	No, notification only

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet 5216		

Product Change Notification						5216 Appliance Outlet	
owner	creation date	release date	released by	change order no	rev	page	D10-004-753
hotzar	2016-06-01	2016-07-08	buerglal	2010168	A	1 of 1	