

**1 Products affected**

| Product hierarchy no. * |     |     | Part no.   | SBU       | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|-----------|--------------------|-------------------|
| SBU                     | PG  | PGU | Type       |           |                    |                   |
| 02                      | 007 | 012 | 0000001400 | 6610.XXXX | Connectors         | 6610              |

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)



**2 Type of change**

To ensure the fixation of the wires, especially for smaller size of conductor, a support on the Cover is necessary.



The fixation is visible only from the inside of the Cover.

**3 Detailed description of change**

OLD



NEW



**4 Reason of change**

The change gives security if smaller sizes of conductors are used.

**5 Released date**

Release of production

Ww 31

**6 Impact of change and recommended action**

Form: Fixation on the Cover  
Fit: n/a  
Function: Fixation of smaller conductors  
Production Site: n/a  
Product Label: n/a

**7 Reference Documents / Attachments**

| Kind of document | Document number | Remarks |
|------------------|-----------------|---------|
| none             |                 |         |

| 6610 new Cover |            |              |             |                  | 0118.2112 |        |
|----------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date  | created by | release date | released by | notification no. | revision  | page   |
| 2012-06-08     | sha        | 2012-08-21   | sha         | 23633            |           | 1 of 1 |